STANDARD ARRIVAL CHART INSTRUMENT (STAR) - ICAO

TRANSITION LEVEL: ❶

SAMARA, RUSSIA
KURUMOCH
RNAV RWY 05



Feet (QNH)	Metres (QFE)
3400	(891)
2900	(739)
2500	(617)
2300	(556)
1900	(434)
1800	(404)
1700	(373)
1600	(343)
1500	(312)

APPROACH	**124.600**
RADAR	**128.000**
TOWER	**118.200**

❶ TRANSITION LEVEL:
- FL050 when QNH is 1013 hPa (760mm mercury column) or above;
- FL060 when QNH is 977 hPa (733mm mercury column) or above, but less than 1013 hPa (760mm mercury column);
- FL070 when QNH is less than 977 hPa (733mm mercury column).

CHANGE: New chart

BEARINGS AND TRACKS ARE MAGNETIC
ALTITUDES AND ELEVATIONS IN *FEET*
DISTANCES IN KILOMETRES