

MOVEMENT AERODROME CHART GROUND ICA0


TOWER

121.800

ARKHANGELSK,

Ð 2.1 ULAA-39 RUSSIA

TALAGI



APRON:

Stands: 1-29

Reinforced-Concrete Surface: PCN 49/R/C/W/T Strength:

TAXIWAYS:

Width: A1, A6 - 16m A, A3 - 14m

> - 18m A4 Α7 - 25m

Surface: A, A1, A3, A4, A6, A7 - Reinforced Concrete

Strength: A, A1, A3,

- PCN 44/R/C/X/T (02 APR - 30 NOV)

- PCN 49/R/C/X/T (01 DEC - 01 APR)

Α7 - PCN 49/R/C/W/T

ACFT types: STANDS:

1-4

Tu-204, Tu-214, B757-200 II-76T, II-76TD 1, 15, 16

B737-300, B737-400, B737-500, B737-600, B737-700, B737-800, Tu-154, II-18, II-114, MD-87

Tu-134, SAAB-2000 22-29

5-20 An-24, An-26, An-30, An-32, An-72, An-74

An-12, Yak-42 21

Yak-40, CRJ-200, ATR-42-500, An-148 1-26

DC-10-30, MD-11 ACFT shall be parked on the apron of

the Ministry of Defence in the presence of vacant stands.

WARNING:

- 1. TWY edge lights are not provided on the south side of TWY A portions located between TWY A1 and TWY A2, TWY A4 and TWY A6.
- 2. Taxi guide line is displaced by 9 m to the south on TWY A portion between TWY A5 and TWY A6.
- 3. II-76, An-12, II-18 ACFT shall taxi strictly along the taxi guide line under inboard engines power.
- 4. Taxiing of ACFT with a wingspan of more than 34.5m along the western part of the apron between stand 7 and stand 13 is PROHIBITED.
- 5. TWY A2 and TWY A5 are withdrawn from service and closed for taxiing.
- 6. Engines warm-up of four-engined ACFT on TWY A1 and TWY A6 is PROHIBITED.
- 7. A 180-degree turn on the runway for class 1 and 2 ACFT is permitted only in the vicinity of TWY A1 and TWY A6.

AIRAC AMDT 04/23

Federal Air Transport Agency