


AERODROME GROUND MOVEMENT
AND AIRCRAFT PARKING CHART - ICAO

TOWER 121.800

ARKHANGELSK, RUSSIA

TALAGI



Not to scale

APRON: Reinforced-Concrete - PCN 49/R/C/W/T
Stands: 1-29
Surface: Reinforced-Concrete
Strength: - PCN 49/R/C/W/T

TAXIWAYS:
Width: A1, A6 - 16m
 A, A3 - 14m
 A4 - 18m
 A7 - 14m
Surface: A, A1, A3, A4, A6 - Concrete
 A7 - Concrete
Strength: A, A1, A3, A4, A6 - PCN 44/R/C/X/T
 A7 - PCN 49/R/C/W/T

ACFT types:
 Tu-204, Tu-214, B757-200
 Il-76T, Il-76TD
 B737-300, B737-400, B737-500, B737-600,
 B737-700, B737-800, Tu-154, Il-18, Il-114, MD-87
 Tu-134, SAAB-2000
 An-24, An-26, An-30, An-32, An-72, An-74
 An-12, Yak-42
 Yak-40, CRJ-200, ATR-42-500, An-148

DC-10-30, MD-11 ACFT shall be parked on the apron of the Ministry of Defence in the presence of vacant stands.

STANDS:
 1
 1, 15, 16
 1-4
 22-29
 5-20
 21
 1-26

- WARNING:**
1. TWY edge lights are not AVBL on the south side of TWY A portions located between TWY A1 and TWY A2, TWY A4 and TWY A6.
 2. Il-76, Tu-154, Tu-134, Il-18, An-12 ACFT shall taxi along all TWY at reduced speed strictly along the taxi guide line, Il-76, Il-18, An-12 ACFT- under inboard engines power.
 3. Taxiing of ACFT with a wingspan of more than 34.5 m along the western part of the apron between stand 7 and stand 13 IS PROHIBITED.
 4. Taxi guide line on TWY A portion from TWY A5 to TWY A6 is displaced by 9m to the south.
 5. TWY A2 CLSD.
 6. TWY A5 is closed due to technical reasons.
 7. Engines warm-up of four-engined ACFT on TWY A1 and TWY A6 IS PROHIBITED.
 8. A 180-degree turn on RWY 08/26 for 1 and 2 class ACFT is permitted only on turn pads at TWY A1 and TWY A6.