
START 120.900 **GROUND** 119.000 APRON 118.800 UFA, RUSSIA

UFA



APRON:

Surface: - Concrete, Asphalt-Concrete

Stands:

Surface: 1, 1A, 2, 3, 3A, 3B - Concrete - Concrete

32-38

4-6, 12, 14-31, 38A - Asphalt-Concrete

7, 8, 8A, 9-11 - Asphalt-Concrete

Strength: 1, 1A, 2, 3, 3A, 3B - PCN 88/R/B/W/T

32-38

- PCN 88/R/B/W/T

4-6, 12, 14-31 - PCN 58/F/D/W/T

7, 8, 8A, 9-11 - PCN 65/F/D/W/T

TAXIWAYS:

Strength: A, H

Width: A, E - 22.5m

> В - 17m

- 16m

D - 23.5m

- 22.5m

F, J - 22.5m

Н - 22.5m

Surface: A, B, C, D, E, H - Asphalt-Concrete

E2, F, J

- Concrete - PCN 107 F/D/W/T

- PCN 65 F/D/W/T В

- PCN 27 F/D/X/T

- PCN 88 R/B/W/T

D, E, F - PCN 83 R/B/W/T

Taxi routes on the Apron:

Route K1: from TWY B to TWY D (PCN 107/F/D/W/T).

Route K2: from TWY D to stand 1A (PCN 88/R/B/W/T).

Taxi routes before take-off:

Route 1: Route K2 - TWY D - crossing RWY 14L/32R by ATS unit clearance - TWY F.

Route 2: Route K1 - TWY D - crossing RWY 14L/32R by ATS unit clearance - TWY F.

Route 3: Route K2 - Route K1 - TWY H - TWY A - crossing RWY 14L/32R by ATS unit

clearance - TWY J.

Route 4: Route K1 - TWY H - TWY A - crossing RWY 14L/32R by ATS unit clearance -- TWY J.

Taxi routes after landing:

Route 5: TWY J - crossing RWY 14L/32R by ATS unit clearance - TWY A - TWY H -

Route K1 - Route K2.

Route 6: TWY J - crossing RWY 14L/32R by ATS unit clearance - TWY A - TWY H -

Route K1.

Route 7: TWY F - crossing RWY 14L/32R by ATS unit clearance - TWY D - Route K2.

Route 8: TWY F - crossing RWY 14L/32R by ATS unit clearance - TWY D - Route K1.

RWY 14L/32R segment from TWY A to TWY D AVBL for ACFT parking. TWY B, C shall only be used for towing of ACFT onto RWY 14L/32R for parking.

 The total width of TWY B and shoulders is 23m, that is less than the required standard width for index 4 ACFT which is 27m. Taxiing of Tu-204, Tu-214, Tu-134, II-114, II-18, An-12, Yak-42, A-319, A-320, A-321-100(200), B757, B727-200 (index 4) ACFT via TWY B shall be carried out at a reduced speed under the flight crew's increased caution, strictly along the TWY centre line.

3. Taxiing of An-124-100 (index 7 ACFT) via TWY F shall be executed only for parking the ACFT on Holding bay of the TWY F. When An-124-100 (index 7 ACFT) is parked on Holding bay of the TWY F, taxiing via TWY F is PROHIBITED. Taxiing of index 6 ACFT via TWY F is permitted when Holding bay of TWY F is not occupied by index 4, 5, 6, 7 ACFT.